

Firmware Build Timestamp: 141215

DSL Physical Layer Driver:

A2pB033h.d23f

Updates/Changes

1. Memory Allocation

Memory Allocation for Management Services restricted

Firmware Build Timestamp: 140912

DSL Physical Layer Driver:

A2pB033h.d23f

Updates/Changes

1. GUI Modification

GUI now properly allows editing for static configurations

NTP failure resolved

Firmware Build Timestamp: 140828

DSL Physical Layer Driver:

A2pB033h.d23f

Updates/Changes

1. GUI Modification

GUI now properly allows editing between WAN Service connection types

Firmware Build Timestamp: 140612

DSL Physical Layer Driver:

A2pB033h.d23f

Updates/Changes

#### 1. PPP Update

Authentication – Will indefinitely attempt re-authentication upon failure

#### 2. WAN Modification BugFix

Rmote Service Access now persistent across WAN modification

#### 3. MTU

Added MTU Modification feature

Default PPPoE: 1492

Default PPPoA: 1500

Default IPOE: 1500

#### 4. Device Summary Link

Logo now contains a link to the device summary page.

Firmware Build Timestamp: 140509

DSL Physical Layer Driver:

A2pB026.d23f

Updates/Changes

#### 1. PPP Update

Authentication – Will indefinitely attempt re-authentication upon failure

#### 2. WAN Modification BugFix

Rmote Service Access now persistent across WAN modification

Firmware Build Timestamp: 140224

DSL Physical Layer Driver:

A2pB026.d23f

Updates/Changes

#### 1. DNS Proxy

Resolve issue with rare cases of DNS Proxy process crashing

Added “DNS WAN IP Relay” for LAN Hosts

#### 2. UPnP

Increased daemon stability under heavy use

3. Ethernet Port Duplex Operations

Updated Duplex Algorithm for auto Half / Full Duplex Switching

4. GUI Modification

X DSL Statistics presentation modified

5. ACS Optimization

Hardened ACS / TR69 Daemon