



# Firmware Release Notes

Model: M405  
Hardware Revision: 2a  
Current Firmware Version: **DQ-R1B043-US.EN**  
DSL PHY Driver: A2pB025a.d20e  
Date: January 25, 2014

## Firmware Release: DQ-R1B043-US.EN

### **Updates / Changes**

- 1 HTTP Cross Site Vulnerability**  
Resolve issue with Cross site security vulnerability

---

## Firmware Release: DQ-R1B042-US.EN

### **Updates / Changes**

- 1 WAN DHCP Option 125**  
Disable option 125 for WAN DHCP Client for compatibility with Cisco Routers

---

## Firmware Release: DQ-R1B041-US.EN

### **Updates / Changes**

- 1 TR-069 ACS Client**  
Updated ACS Client parameters for Clear Access interoperability

---

## Firmware Release: DQ-R1B033-US.EN

### **Updates / Changes**

- 1 PPP Redirect – Dual WAN Setup**  
Updated PPP redirect function to work with dual PPP WAN setup

**Updates / Changes**

**1 PPP Fragmentation**

Resolve issue with PPP Packet Fragmention

---